

Work Order ID 105632

105632

Page 1

August-09-13 2:38:07 PM

Item ID: D350-636-015

Accept

N900040100

Setup Start *NS1*

Revision ID:

Stop *NS2*

Item Name: Skidtube LH Run-on Landing Wearplates Aerazur / Apical Cylindrical Float Compatible

Start Date: 8/08/13 Start Qty: 1.00 *1*

Cust Item ID:

Required Date: 8/09/13 Req'd Qty: 1.00 *1*

Customer: CNATI12

Reference: RMA RA111588 RETURN

Approvals: Process Plan: _____ Date: _____ Tooling: _____ Date: _____

QC: _____ Date: _____ SPC (Y/N): _____ Date: _____

DART Dart Aerospace Ltd. 1270 ABERDEEN ST. HAWKESBURY, ONT. CANADA K6A 1K7		TC APPROVAL # 08-89 TEL: 9-613-632-5200	
P/N	D350-636-015	CHG	CHG004
DESC.	Skidtube LH	STC	SH99-7
LOT	B97393	STC	SR00646SE
MODEL	AS350/355	STC	
PATENTS US # 5735484, CA # 2222184 EUROPE # 16 9-89		MADE IN CANADA 02723-2	

Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
--------------------------------	--------------------------	----------------------	---------	--------	--------------	---------------	---------------	------------------	----------------

Draw Nbr	Revision Nbr
----------	--------------

D3492	C
D4168	A
IIN-D350-636	I

100 0.00

100

QC

Quality Control

Memo

INSPECT RA111588
1 X D350-636-015 B97393

CHG 004

DAS
16
9-89

13/08/30

110 0.00

110

HandFinish

Hand Finishing

Memo

REMOVE D4154-041 WEARPLATE
B97401

TOUCH UP ROCKER GUARD A/R

126850

At 13-9-28

Return to stbe using original B/N

Work Order ID 105632

105632

Page 2

August-09-13 2:38:07 PM

Item ID: D350-636-015 Accept *N900040100* Setup Start *NS1*
 Revision ID: Stop *NS2*
 Item Name: Skidtube LH Run-on Landing Wearplates Aerazur / Apical Cylindrical Float Compatible
 Start Date: 8/08/13 Start Qty: 1.00 *1* Cust Item ID:
 Required Date: 8/09/13 Req'd Qty: 1.00 *1* Customer: CNATI12
 Reference: RMA RA111588

Approvals: Process Plan: _____ Date: _____ Tooling: _____ Date: _____ Run Start *NR1*
 QC: _____ Date: _____ SPC (Y/N): _____ Date: _____ Stop *NR2*

Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
120		0.00							
120						1	0	0	AS
Skidtubes	Memo	0.00							13-9-29
Skidtubes	SCRAP/DESTROY TUBE								
									Gave to Emy
130	QC21- Final Inspection - Work Order Release	0.00							
130									
QC	Memo	0.00							
Quality Control									

AS / Rm 13/10/09

u 130930

Picklist Print

August-09-13 2:38:06 PM

Page 1

Work Order ID: 105632

Parent Item: D350-636-015

Start Date: 8/08/13

Required Date: 8/09/13

Parent Item Name: Skidtube LH Run-on Landing Wearplates Aerazur / Apical Cylindrical Float Compatible

Start Qty: 1.00

Required Qty: 1.00

Comments: IPP rev:A 10.09.28 new issue DD verf:EC IPP Rev:B 11.04.14 ecn11-553
DD verf:EC IPP Rev:C 11.10.18 as per NCR 11-906 DD verf:EC IPP
Rev:D 112.04.16 AS PER ECN 12-542 DD verf:EC

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
D350-636-015		Manufactured	No				Each	0.0000		1	97393	8/1	u
Skidtube LH Run-on Landing Wearplates Aerazur / Apical Cylindrical Float Compatible													
D4154-041		Manufactured	No				Each	5.0000		-1			
Wearplate Assembly													

Location	Loc Qty	Loc Code
FP002	5	
90371	1	
97402	4	

97401

1

1

13-0-30

RA 11588 D350-636-015

Received @ Dart August 2013
Inspected @ Dart August 2013

CUSTOMER: NATIONAL AIRWAYS & FINANCE
CORP
CUSTOMER CONTACT: DARRYL SHOVLIN
SHIPPED FROM: GERMIDTON GAUTENG, ZA

Instructions for RA 11588 D350-636-015 B96277, B97393, B96278

- Due to the fwd bend angles over 2.0° all tubes scrap
 - D350-636-015 B96277 remove D4154-041 B90371
 - Re stock under new Batch # (touch up rocker guard if necessary)
 - D350-636-015 B97393 remove D4154-041 B97401
 - Re stock under new Batch # (touch up rocker guard if necessary)
 - D350-636-015 B96278 remove D4154-041 B94568
 - Re stock under new Batch # (touch up rocker guard if necessary)
- Kits returned were not for these tubes
 - Kits were from B97393, B97391, B97390
 - Return all hard ware and D parts back into stock under original Batch #'s

Time Estimate = 3 HOURS ONLY

Departments Required: Stores & Finishing (dissemble & scrap)

Pictures Attached = NO

QTY INSPECTED = x3 D350-636-015 B96277, B97393, B96278

**THIS INSTRUCTION SHEET MUST
BE ATTACHED TO THE
RESTOCKING WORK ORDER AT
ALL TIMES!!!!**

add in
modifying
Bom

old B/N
RE-APPLY